35 Medford Street Somerville, MA 02143 T: 617.776.6545 F: 617.776.6678 www.hktarchitects.com

Public Facilities Improvement Plan - Fairhaven, MA

# RECEIVED TOWN CLERK

### **MEETING AGENDA**

2018 JUN 15 A 10: 33

HKT Project No.: 21713

FAIRHAVEN. MASS.

**Meeting Title:** Meeting #5

Janet M. Slemenda, HKT Architects

Amy J. Dunlap, HKT Architects

Date: March 27, 2018

Time: 3:00 PM

Attendees: Capital Planning Committee

Please Read / Bring:

**Meeting Facilitators:** 

#### **AGENDA ITEMS**

The objective of this meeting is to review probable costs for individual projects and to discuss timelines and priorities.

- A. Review Minutes.
- B. Review process for Development of Probable Costs.
- C. Review of Individual Projects.
  - (1) Police and Fire Station with Emergency Management, Harbormaster and Animal Shelter
    - (a) Animal Shelter
    - (b) Emergency Management
  - (2) Recreation and Senior Center
  - (3) Town Hall
  - (4) Millicent Library
  - (5) Board of Public Works
  - (6) School Administration
  - (7) Tripp School
  - (8) Fairhaven High School
  - (9) Hastings Middle School
  - (10) East Fairhaven Elementary School
  - (11)Leroy Wood Elementary
- D. Develop Priorities and Timelines.
- E. Schedule.

# Fairhaven Public Facilities Improvement Plan Study Cost Estimate

Fairhaven, Ma

Prepared by:



165 Middlesex Turnpike Suite 106 Bedford, Ma 01730 www.tortoraconsulting.com

Prepared for:

**HKT** 

March 26, 2018

Study Cost Estimate Fairhaven, Ma

March 26, 2018



#### **GENERAL QUALIFICATIONS**

This cost estimate was produced from March 13, 2018 Study memo documents provided by HKT. Design and engineering changes occurring subsequent to the issue of these documents have not been incorporated in this estimate.

This estimate includes all direct construction costs, general contractor's overhead and profit and design contingency. Cost escalation per main summary.

Bidding conditions are expected to be public bidding utilizing chapter 149 filed sub bidding and DCAM qualified general contractors.

The estimate is based on prevailing wage rates for construction in this market and represents a reasonable opinion of cost. It is not a prediction of the successful bid from a contractor as bids will vary due to fluctuating market conditions, errors and omissions, proprietary specifications, lack or surplus of bidders, perception of risk, etc. Consequently the estimate is expected to fall within the range of bids from a number of competitive contractors or subcontractors, however we do not warrant that bids or negotiated prices will not vary from the final construction cost estimate.

#### ITEMS NOT CONSIDERED IN THIS ESTIMATE

Land acquisition, feasibility, and financing costs
Items identified in the design as Not In Contract (NIC)
Items identified in the design as by others
Utility company back charges, including work required off-site
Work to City streets and sidewalks, (except as noted in this estimate)
Construction or occupancy phasing or off hours' work, (except as noted in this estimate)
Rock excavation; special foundations (unless indicated by design engineers)
Contaminated or unsuitable soils removal or replacement

#### Recommendations For Cost Control

TCI recommends that the Owner and Architect carefully review this document, including line item descriptions, unit prices, clarifications, exclusions, inclusions and assumptions, contingencies, escalation and mark-ups.

Request for modifications of any apparent errors or omissions to this document must be made to TCI with in ten (10) days of receipt of this estimate. Otherwise, it will be understood that the contents have been concurred with and accepted.

It is recommended that TCI using bid documents produce a final update estimate, to determine overall costs changes which have occurred since the preparation of the estimate. The final update estimate will address changes and additions to the document, as well as addenda issued during bidding process. TCI cannot reconcile bid results to an estimate not produced from bid documents.

#### Statement Of Probable Cost

TCI has no control over the cost of labor and materials, the general contractor's or any subcontractor's method of determining prices, or competitive bidding and market conditions. The opinion of construction is made on the basis of the experience, qualifications, and best judgment of the professional estimator familiar with the industry. TCI does not guarantee that bids will not vary form this estimate.

TCI staff of professional cost estimators has prepared this estimate in accordance with generally accepted principles and practices.

### Acceptance of Report

With acceptance of this report, the holder shall indemnify and hold harmless Tortora Consulting from and against all claims, damages, losses and expenses, including but not limited to attorney fees and court costs arising out of or as a result of the performance of this work, including third party claims.

Study Cost Estimate Fairhaven, Ma

March 26, 2018



2029 2027 2028 Item # Project 2025 2026 \$499,570 \$461,881 \$480,356 \$427,035 \$444,116 1 Animal Shelter - existing facility at 200 Bridge Street \$2,116,850 \$1,964,697 \$2,039,355 East Fairhaven Elementary School - existing facility at 2 New Boston Road \$1,823,480 \$1,892,772 2 \$132,262 \$137,288 \$142,505 3 Emergency Management Building - existing facility at 150 Sconticut Neck Road \$122,755 \$127,420 \$29,658,521 \$30,785,545 \$28,572,756 Fairhaven High School - existing facility at 12 Huttleston Avenue \$26,519,017 \$27,526,740 \$13,963,582 \$14,494,198 Hastings Middle School - existing facility at 30 School Street \$13,452,391 5 \$12,485,466 \$12,959,914 \$52,376,590 \$48,611,891 \$50,459,143 Joint Fire & Police Station - new site at 194 Bridge Street (includes animal shelter) \$45,117,789 \$46,832,265 \$380,096 \$394,540 \$366,181 7 Leroy Wood Elementary School - existing facility at 60 Sconticut Neck Road \$339,861 \$352,776 \$2,742,314 \$2,846,522 \$2,954,690 Millicent Library - existing facility at 45 Center Street \$2,545,203 \$2,641,921 DPW Building & Facilities – existing facility at 5 Arsene Street (included 8,000 sf veh sto \$6,992,908 \$6,023,771 \$6,252,674 \$6,490,276 \$6,736,906 \$7,018,331 10 Joint Recreation and Senior Center - existing site at 227-229 Huttleston Avenue \$6,045,671 \$6,275,406 \$6,513,871 \$6,761,398 11 \$1,852,918 \$1,923,329 School Administration Building – existing facility at 128 Washington Street \$1,656,777 \$1,719,735 \$1,785,085 12 \$497,252 \$516,148 Town Hall - existing facility at 40 Center Street \$444,616 \$461,511 \$479,048 \$9,680,629 13 Tripp School Building – existing facility at 56 Bridge Street \$8,339,003 \$8,655,885 \$8,984,809 \$9,326,232

Study Cost Estimate

Fairhaven, Ma

March 26, 2018



# Animal Shelter – existing facility at 200 Bridge Street

	55005 0500000000	200000000000000000000000000000000000000			EST'D	SUB	TOTAL
TEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	COST	TOTAL	COST
	Deferred Maintenance Items						
	Further investigation is recommended to determine the cause of the open	227			2 000		
1	CMU joint and	1	ls	5,000.00	5,000		
	concrete walkway cracks at the NE corner of the building. Assume						
	repointing 10LF of CMU mortar joints. Assume removing and replacing 5x5 section of concrete walk.	1	ls	5,000.00	5,000		
	Roof issues/patching has been ongoing. Assume removing and replacing						
2	1000 sf of asphalt shingle roofing and sheathing.	1,000	sf	15.00	15,000		
	Replace 12LF of damaged painted wood trim and section of vinyl soffit with	62726					
3	hole.	12	If	75.00	900		
4	Replace 4 damaged/crushed downspouts.	4	ea	200.00	800		
5	Replace 10x10 residential overhead door with a commercial model.	1	ea	6,500.00	6,500		
6	Replace faded vinyl shutters. Assume 10 shutters 6'H.	10	ea	150.00	1,500		
7	Patch any damaged gypsum wall board and paint all interior walls.	2,119	sf	3.00	6,357		
8	Damaged wall surfaces in cat room should be repaired to facilitate cleaning operations.	2,119	sf	2.00	4,238		
9	Remove and replace FRP panels on 100 sf.	100	sf	15.00	1,500		
10	Replace damaged ACT tiles. Assume 100 2x2 tiles.	400	sf	3.00	1,200		
11	Caulk joint at animal bathing tub should be replaced.	1	Is	500.00	500		
12	Replace cabinets and counters. Assume 9 LF of PLAM base cabinets and counter.	9	lf	400.00	3,600		
13	Install 4' long ramp at the dog kennel door with a door actuator.	1	ls	2,500.00	2,500		
14	Trench drain covers should be replaced with a heel proof style. Assume 70 LF.	70	lf	35.00	2,450		
15	Replace 2 exterior door knobs with lever style hardware.	2	ea	100.00	200		
16	HVAC upgrades	2,119	sf	40.00	84,760		
17	Plumbing- insulate domestic piping	2,119	sf	2.50	5,298		
	Electrical: Provide emergency back-up generator 30kw, 37.5KVA at .8P.F.						
18	with an automatic transfer switch mounted outside adjacent to the service entrance	1	ls	45,000.00	45,000		
	Mark-ups - GC/GR, permits, overhead and profit	1	ls	48,075.75	48,076		
			1550	,	Total	240,379	

1 - Animal Shelter

Study Cost Estimate Fairhaven, Ma

March 26, 2018



# East Fairhaven Elementary School – existing facility at 2 New Boston Road

ITEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
1	VCT was installed over an existing expansion joint. Remove 12"W x 14'L section of VCT. Install new VCT around a new expansion joint cover.	14	lf	200.00	2,800		
2	Existing exterior beam showing signs of rust. Scrape, prep and paint 40 LF of exposed steel beam with high performance paint.	40	If	65.00	2,600		
3	No compressible filler was installed between exterior foundation wall and abutting concrete walk. Install 110 LF of foam expansion joint (EMSEAL type).	110	lf	15.00	1,650		
4	Frost heaves have developed at concrete walk outside three doors where water penetrates joint between floor slab and concrete walk. Remove section of concrete walk at each door (one at 4'W x 15'L and one at 4'W x 30'L), chip away damaged concrete at floor slab edge to create a clean straight edge, repair slab edge, prepare subgrade and install new walk	3	loc	5,000.00	15,000		
5	Existing precast curb has settled and is more than $\chi''$ lower than adjacent sidewalk. Assume removing and replacing 30 LF of precast curb.	30	If	50.00	1,500		
6	Install insulated blank off panel 2'H x 5'W at 25 unit ventilators. Existing electronic security system is two subsystems (access control and	25	ea	500.00	12,500		
7	video surveillance). Upgrade NVR (network video recorder) and consolidate into a single database.	1	Is	25,000.00	25,000		
8	Upgrade interior and exterior lighting to high efficiency LED fixtures.	74,630	sf	10.00	746,300		
9	Plumbing/FP: No action required	9	lf	400.00	3,600		
10	Mechanical: No action required	1	Is	2,500.00	2,500		
	Mark-ups - GC/GR, permits, overhead and profit	1	ls	203,362.50	203,363 Total	1,016,813	

CURRENT 2018 CONSTRUCTION COSTS 1,016,813

Study Cost Estimate Fairhaven, Ma

March 26, 2018



# Emergency Management Building – existing facility at 150 Sconticut Neck Road

TEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
1	Demoliotion of existing building is approximately 3,968 GSF, one story, wood framed with wood, stucco and exposed aggregate concrete siding	3,968	sf	6.00	23,808		
2	Abatement	3,968	sf	2.50	9,920		
3	MEP make safe	1	ls	5,000.00	5,000		
4	Cut and cap utilities and infill site and prep for future use	1	Is	15,000.00	15,000		
	Mark-ups - GC/GR, permits, overhead and profit	1	ls	13,432.00	13,432 Total	67,160	



# Fairhaven High School – existing facility at 12 Huttleston Avenue

	SCOOL DESCRIPTION				EST'D	SUB	TOTAL
TEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	COST	TOTAL	COST
	Deferred Maintenance Items						
	See estimate from Spencer & Vogt Group for 5-year improvement plan to						
1	address known issues with the building envelope. (phase 1 - 5 scope	1	Is	5,632,700.00	5,632,700		
3/	includes mark-ups)	-	.5	3,032,700.00	3,032,700		
2	Clean masonry to remove staining and efflorescence.	1	Is	300,000.00	300,000		
3	Replace all control joints.	1	Is	15,000.00	15,000		
4	Remove moss from flat roofs and clean roof drains.	1	ls	2,500.00	2,500		
5	Restore concrete at entrance ramp.	1	ls	15,000.00	15,000		
6	Paint guardrails at entrance ramp/stair.	1	ls	5,000.00	5,000		
	Seal all joints between precast cap sections at main entrance stair/ramp.	_		3,000.00	3,000		
7	Clean concrete walls to remove staining.	1	Is	15,000.00	15,000		
8	Replace carpet in library.	10,000	sf	5.00	FO 000		
9	Replace broken VCT tiles in meeting room.	17.0			50,000		
10	Replace broken ceramic tiles in toilet rooms.	1	ls Is	1,500.00	1,500		
11	Complete plaster ceiling repair work.	1	ls	1,500.00	1,500		
12	Remove and replace resilient stair treads in main stair.	1	ls	25,000.00	25,000		
13	Install handrails at stairs where they are lacking.	1	ls	15,000.00 25,000.00	15,000		
13	Remove rust and repaint fire escapes. Consider using a more high	1	15	25,000.00	25,000		
14	performance industrial paint to prevent rusting and improve coating	1	ls	75,000.00	75 000		
14	longevity.	1	IS	75,000.00	75,000		
	Install drywells outside three doors at recessed areaways to control						
	flooding. Conduct video investigation of storm drain system to determine if						
15	any blockages are causing backups. Install removable flood gate panels at	1	Is	30,000.00	30,000		
	double doors to mechanical room.						
	Extend boiler exhaust running on exterior of building 30' vertically to be						
16	higher than operable windows.	1	Is	10,000.00	10,000		
	Provide an air balancing report of the entire building to verify code						
17	compliant ventilation is being provided.	145,470	sf	2.00	290,940		
	compliant ventuation is being provided.						
18	Upgrade controls to full BMS throughout. Existing controls are pneumatic.	145,470	sf	6.00	872,820		
19	Heating system replacement	145,470	sf	25.00	3,636,750		
	Electrical: Upgrade to LED light sources. Add occupancy and photo dimming	10			18000 18 100		
20	sensors.	145,470	sf	10.00	1,454,700		
	Plumbing: Replace plumbing fixtures with water conservation type. Typical						
21	for 23 toilets, 10 urinals, 23 lavatories, 28 misc. sinks, 7 mop sinks and 12	104	ea	2,500.00	260,000		
	showers			5.00 m	state is the interest of the		
	Mark-ups - GC/GR, permits, overhead and profit (items 15-21)	1	ls	1,775,177.50	1,775,178		
	mark aps - 36, on, permits, overhead and profit fiterins 13-21)	1	13	1,773,177.30	1,775,178 Total	14,508,588	
					iotai	14,300,300	

CURRENT 2018 CONSTRUCTION COSTS 14,508,588

Study Cost Estimate Fairhaven, Ma

March 26, 2018



# Hastings Middle School – existing facility at 30 School Street

1751.5	SCORE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
ITEM	SCOPE DESCRIPTION	QUANTITY	UNII	CO31/3F	COST	TOTAL	2031
1	Roof requiring replacement	40,000	sf	30.00	1,200,000		
2	Demolish modular unit used for a teachers' room that needs to be demolished	1	ls	30,000.00	30,000		
3	Renovate spare classroom to make a teachers' room.	1	ls	15,000.00	15,000		
4	Regrading or ramps would be required at about 8 locations to make egress accessible.	8	ea	5,000.00	40,000		
5	Assume HVAC systems upgrades/replacement.	94,005	sf	30.00	2,820,150		
6	Install bi-level drinking fountains.	4	ea	5,000.00	20,000		
7	Create accessible seating in Auditorium.	1	Is	5,000.00	5,000		
8	Add accessible toilets in gym lobby and nurse's office	2	loc	3,500.00	7,000		
	<u>Deferred Maintenance Items</u>						
9	Repoint stone pier at main entrance.	1	ls	5,000.00	5,000		
10	Remove rust from steel lintels above windows, doors and unit ventilator louvers and paint.	1	ls	75,000.00	75,000		
11	Repair masonry where lintels have caused cracking and displacement.	1	ls	100,000.00	100,000		
12	Remove and replace all deteriorated sealant (mostly at window sills) and expansion joints.	1	Is	50,000.00	50,000		
13	Repaint all wood trim, exposed steel and other painted surfaces.	1	ls	150,000.00	150,000		
14	Replace plywood panels at basement openings with prefinished insulated metal panels.	1	ls	75,000.00	75,000		
15	Replace missing gaskets at exterior doors.	1	ls	10,000.00	10,000		
16	Patch damaged soffit at main entrance and paint.	1	ls	5,000.00	5,000		
17	Repair/replace damaged vents at unit ventilators.	1	Is	5,000.00	5,000		
18	Repair spalled concrete steps and foundation cracks.	1	Is	10,000.00	10,000		
19	Replace damaged downspouts and protect from future damage to allow free drainage from the roof.	1	Is	5,000.00	5,000		
20	Reset loose quarry tiles at lockers. Replace missing ceramic tiles in kitchen.	1	ls	2,500.00	2,500		
21	Regrout ceramic tile toilet room walls where required.	1	Is	2,500.00	2,500		
22	Extend partition at Room 1B to the underside of decking.	1	Is	5,000.00	5,000		
23	Refinish damaged wood doors.	1	ls	15,000.00	15,000		
24	Refinish classroom casework and replace hardware with AAB/ADA compliant.	1	Is	50,000.00	50,000		
	Repair spalling/shearing concrete egress stairs from auditorium and						
25	regrade or add additional step where bottom riser is too tall. Install compliant guardrails.	1	ls	25,000.00	25,000		
26	Install compliant guardrails at areaway.	1	ls	10,000.00	10,000		
27	Install handrails at exterior steps at egress doors.	1	ls	7,500.00	7,500		
28	Continue planned window replacement.	1	ls	300,000.00	300,000		
29	Replace carpet in offices.	30,000	sf	5.00	150,000		
30	Replace ACT ceilings in classrooms and offices.	45,000	sf	6.00	270,000		
	Mark-ups - GC/GR, permits, overhead and profit	1	Is	1,366,162.50	1,366,163 Total	6,830,813	

CURRENT 2018 CONSTRUCTION COSTS 6,830,813

Study Cost Estimate Fairhaven, Ma

March 26, 2018



# Joint Fire & Police Station – new site at 194 Bridge Street (includes animal shelter)

ITEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
	Police/Fire						
1	2 story and basement Police/Fire Station	48,500	sf	400.00	19,400,000		
2	Typical sitework - 20% of building costs (earthwork, utilities and all site finishes)	1	Is	3,880,000.00	3,880,000	23,280,000	
	Total Typical Buildings and Site - \$/sf	48,500	sf	480.00	23,280,000		
	Animal Shelter						
3	Woood framed structure, dog run	3,200	sf	275.00	880,000		
4	Typical sitework - 20% of building costs (earthwork, utilities and all site finishes)	1	Is	176,000.00	176,000	1,056,000	
	Total Typical Buildings and Site - \$/sf	3,200	sf	330.00	1,056,000		
	Premium cost related to site location						
5	Demolition of existing animal shelter	3,200	sf	15.00	48,000		
6	Phasing & relocations	1	ls	300,000.00	300,000	348,000	
			A BA	CURR	ENT 2018 CONSTRU	UCTION COSTS	24,684,000

#### Notes:

- a. Sitework costs do not assume large quantities of ledge blasting, unsuitable soil replcement or hazardous soil remediation
- Sitework costs assumptions are as follows:

   (Low) 10% Sites formally developed with existing utilities and no known site complications such as ledge or significant cut/fill
   (Medium) 15% Sites with moderate slopes, some cut/fill
   (High) 20% Sites with no utilities and excessive site complications, blasting and soil replacement

Study Cost Estimate Fairhaven, Ma

March 26, 2018



### Leroy Wood Elementary School – existing facility at 60 Sconticut Neck Road

ITEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
1	New cast in place concrete site stair connecting existing concrete sidewalks. Existing elevation change is approximately 6'-0". Assume 1' cheek walls and 4' wide stair with painted galvanized steel handrails	1	ls	25,000.00	25,000		
2	Existing precast curb has settled and is more than %" lower than adjacent sidewalk. Assume removing and replacing with new precast curb	1,650	If	75.00	123,750		
3	Mechanical: No action required.						
4	Electrical: No action required.						
5	Plumbing/FP: No action required.						
	Mark-ups - GC/GR, permits, overhead and profit	1	ls	37,187.50	37,188 Total	185,938	
93				CURRI	ENT 2018 CONSTR	UCTION COSTS	185,9

Study Cost Estimate Fairhaven, Ma

March 26, 2018



# Millicent Library – existing facility at 45 Center Street

ITEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
	Mechanical:						
1	Add a preheat coil or a unit heater at the combustion air intake to prevent freezing temperatures in the Mechanical Room and at the Water Mains.	1	ls	7,500.00	10,000		
2	Provide Mechanical ventilation upgrades throughout the building.	15,489	sf	25.00	387,225		
3	Consider adding AC to the remaining portions of the building that currently do not have it (spaces not served by the existing RTUS).	15,489	sf	15.00	232,335		
4	Provide a building management system, or controls upgrade for 7-day programmable occupied and unoccupied modes with remote monitoring and adjustment.	15,489	sf	5.00	77,445		
5	Electrical: The tel/data system should be upgraded and wiring run concealed where possible or in EMT painted and terminated in an IDF rack to industry	15,489	sf	3.00	46,467		
6	standards with appropriate power and conditioning.  The lighting may have some historical significance and refurbishing cleaning and relamping would be required.  Plumbing/FP:	15,489	sf	20.00	309,780		
7	Relocate domestic water meter from current location adjacent to the combustion air louver.	1	ls	3,500.00	3,500		
8	Replace antiquated domestic water shutoff valves.	1	İs	1,500.00	1,500		
9	Insulate domestic water piping.	15,489	sf	1.50	23,234		
0	Provide new accessible plumbing fixtures. Typical for 2 toilets, 2 lavatories, 3 kitchen style sinks	7	ea	2,500.00	17,500		
1	Provide drinking fountain.	1	ea	5,000.00	5,000		
	Mark-ups - GC/GR, permits, overhead and profit	1	ls	278,496.50	278,497 Total	1,392,483	

8 - Millicent Library



# DPW Building & Facilities – existing facility at 5 Arsene Street (included 8,000 sf veh stor)

New free standing 8,000 GSF vehicle storage building to be built on existing site.   2 Proposed interior renovations of office area   2,800   sf   125.00   350,000	ITEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
Site   Sproposed interior renovations of office area   2,800   3   250,000   2,000,000								
Proposed interior renovations of office area   2,800   sf   125.00   350,000	1		8,000	sf	250.00	2,000,000		
Perform   Maintenance   Nems   Seplace broken glass at transom (3"W x 7"H).   1 ea   350.00   3,000	2		2 800	cf	125.00	350,000		
Replace damaged verteend door panels. Assume six panels 2"H x 12"W. 6	2		2,000	31	125.00	330,000		
4 Replace damaged overhead door panels. Assume six panels 2"H x12"W.         6         ea         500.00         3,000           5 Replace damaged/forther wood trim at overhead doors.         15         ea         250.00         3,750           6 Replace flooring as per 5 year plan. Assume 4,170 SF of existing VCT removed and replaced with finoleum.         4,170         sf         10.00         41,700           7 Paint interiors         5,000         sf         2.50         12,500           8 Replace acoustic ceiling tiles throughout         5,000         sf         2.50         25,000           9 Replace tollet partitions with plastic or metal partitions         6         ea         1,200,00         7,200           10 2"H beam.         2"H beam.         2"T beam.         27         ea         100.00         2,700           12 Replace Unch room cabinets/sink with accessible design. Assume 14 LF of plastic laminate wall and base cabinets with solid surface counter.         14         if         500.00         7,000           13 Upgrade controls in administration area.         20,758         sf         3.00         62,274           4 Provide code complant were traillation throughout the building including exhaust in the garage and tollet/shower/locker rooms.         20,758         sf         0.50         103,790           1 Electrical: Upgrades required:	3		1	ea	350.00	350		
Assume 3"H trim replaced at each jamb of 15 overhead doors. Trim is painted 1x6. Replace flooring as per 5 year plan. Assume 4,70 SF of existing VCT removed and replaced with linoleum. Paint interiors Replace acoustic ceiling tiles throughout Replace cloite partitions with plastic or metal partitions Replace damaged and missing fireproofing on steel. Assume 35 LF at 2"H beam. Replace door knobs with lever trim. Assume 27 doors. Replace lunch room cabinets/sink with accessible design. Assume 14 LF of plastic laminate wall and base cabinets with sold surface counter. Mechanical: Upgrades required: Upgrade controls in administration area. 20,758 sf 3.00 62,274 Replace door knobs with the with sold surface counter. Mechanical: Upgrades required: Upgrade controls in administration area. 20,758 sf 3.00 62,274 Replace door door plant ventilation throughout the building including exhaus in the garge and toilet/shower/plocker rooms. Provide a building management system throughout the building. Replace door look in administration area. Upgrades required: CFCI protected receptacles should be installed where required by the NEC. Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy New Cafe tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements. Plumbing/FP: Upgrades required: Replace existing plumbing fixtures with new accessible water conserving type fixtures. Replace existing plumbing fixtures with new accessible water conserving type fixtures. Replace existing plumbing fixtures with new accessible water conserving type fixtures. Replace existing plumbing fixtures with new accessible water conserving type fixtures. Replace electric beli. In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads. Add		, , ,	6	ea	500.00	3,000		
Assume 3'H trim replaced at each jamb of 15 overhead doors.  Replace flooring as per 5 year plan. Assume 4,170 5 of existing VCT removed and replaced with lincleum.  Paint interiors  Replace acoustic ceiling tiles throughout  Replace toilet partitions with plastic or metal partitions  Replace toilet partitions with plastic or metal partitions  Replace door knobs with lever trim. Assume 27 doors.  Replace door knobs with lever trim. Assume 27 doors.  Replace lunch room cabinets/sink with accessible design. Assume 14 LF of plastic laminate wall and base cabinets with solid surface counter.  Mechanical: Upgrades required:  Upgrade controls in administration area.  Provide code compliant ventilation throughout the building including exhaust in the garage and toillet/shower/locker rooms.  Provide a building management system throughout the building.  Provide a building management system throughout the building.  Provide a building management system throughout the building.  Provide code compliant ventilation throughout the building.  Provide a building management system throughout the building.  Provide code to building management system throughout the building.  Provide code compliant ventilation throughout the building.  Provide code compliant ventilation throughout the building.  Provide code to building management system throughout the building.  Provide code compliant ventilation throughout the building.  Provide	-		15		350.00	2.750		
removed and replaced with linoleum.  Paint interiors  Replace acoustic ceiling tiles throughout  Replace acoustic ceiling tiles throughout  Replace tollet partitions with plastic or metal partitions  Replace door knobs with lever trim. Assume 37 LF at 21 beam.  Replace door knobs with lever trim. Assume 27 doors.  Replace lunch room cabinets/sink with accessible design. Assume 14 LF of plastic laminate wall and base cabinets with solid surface counter.  Mechanical: Upgrades required:  Upgrade controls in administration area.  Very door of the same and tollet/shower/locker rooms.  Provide a building management system throughout the building.  Effective 12 Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  Manual transfer switch with a generator tap box  New Cats tel/data wiring shall be provided and run to a data rack with panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace earting ubase required:  Replace door knobs with lever trim.  Replace door knobs with lever trim. Assume 27 doors.  20,758 sf 3.00 62,274  1 ea 5,000.00 5,000  Sooo 20,000  Agence of the door with a generator tap box  New Cats tel/data wiring shall be provided and run to a data rack with panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  1 ea 2,500.00 45,000  Edward of order drinking fountain.  1 ea 5,000.00 5,000  Mark-ups - GC/GR, permits, overhead and profit  1 is 259,122.50 259,123	5	Assume 3'H trim replaced at each jamb of 15 overhead doors.	15	ea	250.00	3,750		
Paint interiors	6	Replace flooring as per 5 year plan. Assume 4,170 SF of existing VCT	4 170	cf	10.00	41 700		
Replace acoustic ceiling tiles throughout Replace Tolicy partitions with plastic or metal partitions Replace acoustic ceiling tiles throughout Replace dord knobs with lever trim. Assume 35 LF at 2/H beam. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace Controls in administration area.  12 Upgrade controls in administration area. 20,758 sf 3.00 62,274  Provide ocde compliant ventilation throughout the building exhaust in the garage and toilet/shower/locker rooms. Provide a building management system throughout the building. Replace lectrical: Upgrades required:  16 GFCI protected receptacles should be installed where required by the NEC. Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box New Cats tel/data wiring shall be provided and run to a data rack with panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  20,758 sf 3.00 5,000  8 Replace entiquated shutoff valves on domestic water system.  1 ea 2,500.00 45,000  1 ea 2,500.00 5,000  1 any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  20,758 sf 0.75 15,569  20,758 sf 0.75 15,569  20,759 sp.122.50 259,123		removed and replaced with linoleum.	45			2000-200-200-		
Replace toilet partitions with plastic or metal partitions Repair/replace damaged and missing fireproofing on steel. Assume 35 LF at 2 He barn. Replace door knobs with lever trim. Assume 27 doors. Replace door knobs with lever trim. Assume 27 doors. Replace unch room cabinets/sink with accessible design. Assume 14 LF of plastic laminate wall and base cabinets with solid surface counter.  Mechanical: Upgrades required: Upgrade controls in administration area. 20,758 sf 3.00 62,274 Provide code compliant ventilation throughout the building including exhaust in the garage and toilet/shower/locker rooms. Provide a building management system throughout the building. 20,758 sf 5.00 103,790 Electrical: Upgrades required:  GFCI protected receptacles should be installed where required by the NEC. District of the provide and wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements. Plumbing/PP- Upgrades required: Replace entity lated shutoff valves on domestic water system. Replace entity lated shutoff valves on domestic water system. Replace entity lated shutoff valves on domestic water system. Replace entity lated shutoff valves on domestic water system. Replace entity lated shutoff valves on domestic water system. Replace entity lated shutoff valves on domestic water system. Replace entity lated shutoff valves on domestic water system. Replace electric bell. In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads. Add missing cap to fire department connection.  Page 12,500.00 200 Replace existing of the provided and profit 1 is 259,122.50 259,123								
Repair/replace damaged and missing fireproofing on steel. Assume 35 LF at 2/H beam.  Replace door knobs with lever trim. Assume 27 doors.  Replace door knobs with lever trim. Assume 27 doors.  Replace lunch room cabinets/sink with accessible design. Assume 14 LF of plastic laminate wall and base cabinets with solid surface counter.  Mechanical: Upgrades required:  Upgrade controls in administration area.  Provide code compliant ventilation throughout the building including exhaust in the garage and toilet/shower/locker rooms.  Provide a building management system throughout the building.  Electrical: Upgrades required:  16 GFCI protected receptacles should be installed where required by the NEC.  Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box New Cafte 1el/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  Replace antiquated shutoff valves on domestic water system.  Replace antiquated shutoff valves on domestic water system.  Replace electric bell.  Replace electric bell.  Replace electric bell.  Replace electric bell.  Rank-ups - GC/GR, permits, overhead and profit  Rank-ups - GC/GR, permits, overhead and profit  1 lea 200.00 200		이 경우리 사람이 가는 사람이 되었다면 하다면 아이들에게 다 가는 것이 되었다.						
2'H beam. Replace door knobs with lever trim. Assume 27 doors. 27 ea 100.00 2,700 Replace lunch room cabinets/sink with accessible design. Assume 14 LF of plastic laminate wall and base cabinets with solid surface counter.  Mechanical: Upgrades required:  10 Upgrade controls in administration area. Provide code compliant ventilation throughout the building including exhaust in the garage and toilet/shower/locker rooms. 20,758 sf 5.00 103,790 Electrical: Upgrades required:  11 Frovide a building management system throughout the building. 20,758 sf 5.00 103,790 Electrical: Upgrades required:  12 Provide a building management system throughout the building. 20,758 sf 0.50 103,790 Electrical: Upgrades required:  13 Electrical: Upgrades required:  14 Provide a building management system throughout the building. 20,758 sf 0.50 10,379 Electrical: Upgrades required:  15 GFCI protected receptacles should be installed where required by the NEC. 20,758 sf 0.50 10,379  16 GFCI protected receptacles should be installed where required by the NEC. 20,758 sf 0.50 20,758  17 packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box	9		6	ea	1,200.00	7,200		
Replace door knobs with lever trim. Assume 27 doors.	10		35	lf	50.00	1,750		
Replace lunch room cabinets/sink with accessible design. Assume 14 LF of plastic laminate wall and base cabinets with solid surface counter.  Mechanical: Upgrades required:  10 Upgrade controls in administration area.  11 Upgrade controls in administration area.  12 Provide code compliant ventilation throughout the building including exhaust in the garage and toilety-shower/locker rooms.  13 Upgrades compliant ventilation throughout the building including exhaust in the garage and toilety-shower/locker rooms.  14 Provide a building management system throughout the building.  15 Provide a building management system throughout the building.  16 GFCI protected receptacles should be installed where required by the NEC.  17 Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box 1 ea 5,000.00 5,000  19 New Cat6 tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements.  19 Plumbing/FP: Upgrades required:  20 Replace existing plumbing fixtures with new accessible water conserving type fixtures.  20 Replace existing plumbing fixtures with new accessible water conserving type fixtures.  21 Replace antiquated shutoff valves on domestic water system. 1 ea 1,200.00 1,200  22 Replace "out of order" drinking fountain.  20,758 sf 0.75 15,569  20,759 place antiquated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  20,758 sf 0.75 15,569  20,759 place antiquated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.	11		27	00	100.00	2 700		
plastic laminate wall and base cabinets with solid surface counter.  Mechanical: Upgrades required:  10 Uggrade controls in administration area.  20,758 sf 3.00 62,274  Provide code compliant ventilation throughout the building including exhaust in the garage and toilet/shower/locker rooms.  Provide a building management system throughout the building.  Provide code compliant ventilation throughout the building.  Provide code compliate ventilation throughout the building.  Provide code compliate ventil	11		21	ea	100.00	2,700		
Mechanical: Upgrades required:  13 Upgrade controls in administration area.  Provide code compliant ventilation throughout the building including exhaust in the garage and toilet/shower/locker rooms.  Provide a building management system throughout the building. Electrical: Upgrades required:  6FCI protected receptacles should be installed where required by the NEC.  Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy.  18 Manual transfer switch with a generator tap box  New Cato Etel/data wiring shall be provided and run to a data rack with path panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  18 Replace antiquated shutoff valves on domestic water system.  19 Replace "out of order" drinking fountain.  10 Replace of "out of order" drinking fountain.  11 ea 1,200.00 1,200  12 Replace antiquated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  19 Add missing cap to fire department connection.  10 ea 20,758 sf 0.75 15,569  20,758 sf 0.75 25,9123	12		14	lf	500.00	7,000		
Upgrade controls in administration area.  10		The same transfer of the same						
Provide code compliant ventilation throughout the building including exhaust in the garage and toilet/shower/locker rooms.  Provide a building management system throughout the building. Electrical: Upgrades required:  16 GFCI protected receptacles should be installed where required by the NEC.  Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box  New Cat6 tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  1 Replace antiquated shutoff valves on domestic water system.  1 ea 1,200.00 1,200  Replace "out of order" drinking fountain.  1 ea 2,500.00 5,000  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Mark-ups - GC/GR, permits, overhead and profit  1 Is 259,122.50 259,123	13		20,758	sf	3.00	62,274		
exhaust in the garage and toilet/shower/locker rooms.  Provide a building management system throughout the building.  Electrical: Upgrades required:  GFCI protected receptacles should be installed where required by the NEC.  Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace electric bell. Replace electric bell. In ea 1,000.00 1,000 In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Mark-ups - GC/GR, permits, overhead and profit  20,758 sf 3.00 62,274  1 ea 2,500.00 45,000 1,000 1,000 1,000 1,000 20,00	101		0.0000000000000000000000000000000000000		2 22			
Electrical: Upgrades required:  16 GFCI protected receptacles should be installed where required by the NEC. 20,758 sf 0.50 10,379  Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  18 Replace existing plumbing fixtures with new accessible water system.  19 Replace "out of order" drinking fountain.  10 Pagiace "out of order" drinking fountain.  11 Pagiace antiquated shutoff valves on domestic water system.  12 Replace "out of order" drinking fountain.  13 Pagiace "out of order" drinking fountain.  14 Pagiace "out of order" drinking fountain.  15 Pagiace "out of order" drinking fountain.  16 Pagiace "out of order" drinking fountain.  17 Pagiace "out of order" drinking fountain.  18 Pagiace "out of order" drinking fountain.  19 Pagiace "out of order" drinking fountain.  20 Pagiace "out o	14		20,758	st	5.00	103,790		
Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements. Plumbing/FP: Upgrades required: Replace existing plumbing fixtures with new accessible water conserving type fixtures.  18 Replace antiquated shutoff valves on domestic water system.  19 Replace out of order drinking fountain.  20 Replace evisting plumbing fixtures with new accessible water conserving the panels of	15	Provide a building management system throughout the building.	20,758	sf	3.00	62,274		
Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  18 ea 2,500.00 45,0		Electrical: Upgrades required:						
Lighting should be upgraded to high efficiency LED with higher Lumen packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  18 ea 2,500.00 45,0	16	GECL protected recentacles should be installed where required by the NEC	20 758	sf	0.50	10 379		
packages in Equipment Storage and Wash Bay. Lighting controls such as occupancy sensors and daylight dimming sensors should be installed to further reduce energy  Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with  patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  Replace entiquated shutoff valves on domestic water system.  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  1 ls 259,122.50  207,580  1 0.00  207,580  20,758 sf 10.00  20,758  20,758 sf 10.00  20,758  20,758 sf 0.75  20,758  20,758  20,758  20,758  20,758  21,000.00  22,758  23,000.00  24,000  25,000  26,000  27,580  28,000.00  29,000  200  200  200  200  200	10		20,730	31	0.50	10,373		
occupancy sensors and daylight dimming sensors should be installed to further reduce energy  18 Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with  19 patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  18 ea 2,500.00 45,000 type fixtures.  20 Replace antiquated shutoff valves on domestic water system.  1 ea 1,200.00 1,200 Each condition of order drinking fountain.  21 Replace electric bell.  1 ea 5,000.00 5,000 Each condition of the provided and run to a data rack with new accessible water conserving type fixtures.  21 Replace antiquated shutoff valves on domestic water system.  22 Replace "out of order" drinking fountain.  23 Replace electric bell.  1 ea 5,000.00 5,000 Each condition of the provided and provided sprinkler heads with new quick response type sprinkler heads.  24 Add missing cap to fire department connection.  25 Add missing cap to fire department connection.  26 The provided sprinkler heads with new accessible water conserving type sprinkler heads type sprinkler heads with nea								
further reduce energy  Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with  patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  Replace antiquated shutoff valves on domestic water system.  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  1 ea 5,000.00  5,000  45,000  45,000  45,000  1,200  1,200  1,000  1,000  1,000  1,000  20,758  3f  0.75  15,569  20,500  200  Mark-ups - GC/GR, permits, overhead and profit  1 ls 259,122.50  259,123	17		20,758	sf	10.00	207,580		
Manual transfer switch with a generator tap box New Cat6 tel/data wiring shall be provided and run to a data rack with  patch panels in a secure location with appropriate power and conditioning requirements. Plumbing/FP: Upgrades required: Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  Replace "out of order" drinking fountain.  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  1 ea 5,000.00 5,000  5,000 45,000  45,000 1,200  1,200 5,000  1,000 1,000  200 200								
New Cat6 tel/data wiring shall be provided and run to a data rack with  19 patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  10 Replace antiquated shutoff valves on domestic water system.  11 ea 1,200.00 1,200 22 Replace "out of order" drinking fountain.  12 Replace electric bell.  13 Replace electric bell.  14 In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  15 Add missing cap to fire department connection.  16 Add missing cap to fire department connection.  17 In any renovated and profit and	10	S,			F 000 00	F 000		
patch panels in a secure location with appropriate power and conditioning requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  Replace "out of order" drinking fountain.  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  Plumbing/FP: Upgrades sf 3.00 62,274  18 ea 2,500.00 45,000  1,200  1,200  1,000  20,758 sf 0.75 15,569  20,758 sf 0.75 25,123	18	· ·	1	ea	5,000.00	5,000		
requirements.  Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  Replace "out of order" drinking fountain.  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  Replace evisting 18 ea 2,500.00 45,000 1,200 1,200 1,200 1,000 1	19		20 758	sf	3.00	62 274		
Plumbing/FP: Upgrades required:  Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  Replace "out of order" drinking fountain.  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  Replace existing plumbing fixtures with new accessible water conserving 18 ea 2,500.00 45,000  1,200  5,000  1,000  20,758 sf 0.75 15,569  20,758 sf 0.75 25,122.50 259,123	13	**************************************	20,730	31	3.00	02,274		
Replace existing plumbing fixtures with new accessible water conserving type fixtures.  Replace antiquated shutoff valves on domestic water system.  Replace "out of order" drinking fountain.  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  Replace existing plumbing fixtures with new accessible water conserving 18 ea 2,500.00 45,000  1,200  5,000  200  200  200  45,000  1,200  1,000  5,000  1,000  1,000  20758  Sf 0.75  15,569  259,122.50  259,123								
type fixtures.  18 ea 2,300.00 45,000  21 Replace antiquated shutoff valves on domestic water system.  22 Replace "out of order" drinking fountain.  23 Replace electric bell.  1 ea 1,000.00 5,000  24 In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  24 Add missing cap to fire department connection.  25 Mark-ups - GC/GR, permits, overhead and profit  1 ls 259,122.50 259,123								
Replace "out of order" drinking fountain.  Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  1 ea 5,000.00 5,000  1,000  20,758 sf 0.75 15,569  20,758 sf 0.75 200.00  200  200  200	20		18	ea	2,500.00	45,000		
Replace electric bell.  In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  Add missing cap to fire department connection.  Mark-ups - GC/GR, permits, overhead and profit  1 ea 1,000.00 1,000  20,758 sf 0.75 15,569  1 ea 200.00 200  1 ls 259,122.50 259,123	21	Replace antiquated shutoff valves on domestic water system.	1	ea	1,200.00	1,200		
In any renovated space, replace existing 35 year old sprinkler heads with new quick response type sprinkler heads.  20,758 sf 0.75 15,569  24 Add missing cap to fire department connection.  1 ea 200.00 200  Mark-ups - GC/GR, permits, overhead and profit 1 ls 259,122.50 259,123	22	Replace "out of order" drinking fountain.	1	ea	5,000.00	5,000		
new quick response type sprinkler heads.  20,758 sf 0.75 13,569  25 Add missing cap to fire department connection.  1 ea 200.00 200  Mark-ups - GC/GR, permits, overhead and profit 1 ls 259,122.50 259,123	23	Replace electric bell.	1	ea	1,000.00	1,000		
new quick response type sprinkler heads.  25 Add missing cap to fire department connection.  1 ea 200.00 200  Mark-ups - GC/GR, permits, overhead and profit  1 ls 259,122.50 259,123	24	In any renovated space, replace existing 35 year old sprinkler heads with	20.758	sf	0.75	15 569		
Mark-ups - GC/GR, permits, overhead and profit 1 ls 259,122.50 259,123		new quick response type sprinkler heads.		31		Strategy Control (Strategy Con		
	25	Add missing cap to fire department connection.	1	ea	200.00	200		
		Mark-ups - GC/GR, permits, overhead and profit	1	ls	259,122.50	259,123		
		A STATE OF THE STA			revisions Spreekillistiitiitiili	The state of the s	3,295,613	

CURRENT 2018 CONSTRUCTION COSTS 3,295,613



#### Joint Recreation and Senior Center – existing site at 227-229 Huttleston Avenue

ITEAA	SCORE DESCRIPTION	QUARTITY	LIAUT	COST/ST	EST'D	SUB	TOTAL
ITEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	COST	TOTAL	COST
1	New additions:		- 7	F00.00	407.005		
1	Recreation Center to receive approximately 990 GSF addition. Senior Center to receive two additions. Addition to the east is 1,300 GSF.	990	sf	500.00	495,000		
2	Addition to the south is 1,760 GSF.	3,060	sf	500.00	1,530,000		
	Electrical: If a building expansion was to be provided, then a new single						
3	electric service would be recommended. The existing panels would be	1	ls	75,000.00	75,000		
	backfed from the new service switchgear.  Interior renovations:						
0.00	Recreation Center: One storage room to be converted to an office	10000	- 25		1907 100 100 100 100 100 100 100 100 100 1		
4	(approximately 100 sf).	100	sf	200.00	20,000		
5	Senior Center: Approximately 550 sf of enclosed multipurpose room to be	550	sf	200.00	110,000		
	renovated into Lounge/Presentation space. Renovated offices are approximately 450 sf. Light renovations needed here						
6	(paint, flooring) as there is no change to walls/doors, etc.	450	sf	150.00	67,500		
	Deferred Maintenance Items at Senior Center:						
7	Repair cracked sidewalks at entrances. Assume 100LF.	100	lf	25.00	2,500		
8	Reattach loose shingles. Assume 100SF.	100	sf	25.00	2,500		
9 10	Plan for painting of exterior wood siding. See existing elevations.  Repair/replace parged foundation wall insulation. Assume 80SF.	12,546 80	sf sf	1.75 50.00	21,956 4,000		
	Plan for replacement of plastic laminate cabinets (wall and base) and						
11	counters. Assume 62 If	62	lf	500.00	31,000		
	Roofing inspection by a roofing contractor should be performed to						
12	determine the cause of black staining (possible extractive bleeding or algae		le.	F 000 00	F 000		
12	growth). Debris should be removed regularly from gutters and gutters should be inspected for condition. Dented downspouts should be	1	ls	5,000.00	5,000		
	repaired/replaced to allow free stormwater flow.						
	Mechanical: Existing grade mounted air handling unit and all digital						
12	controls have surpassed life expectancy and should be replaced. Existing	12.546	-6	10.00	125 450		
13	indoor air handling unit including the air cooled condenser is approaching	12,546	sf	10.00	125,460		
	life expectancy and should be replaced. Replace with similar types.						
14	Electrical: Install new emergency back-up generator to serve both Senior	1	ls	75,000.00	75,000		
	Center and Recreation Center (none existing).	-	,5	73,000.00	,5,000		
15	Plumbing/FP: Replace all plumbing fixtures with water conservation type.	28	ea	2,500.00	70,000		
	No sprinkler system exists. Extend existing sprinkler system in Recreation			to activities.			
16	Center to Senior Center.	12,546	sf	8.00	100,368		
47	Deferred Maintenance Items at Recreation Center:		16				
17	Repair cracked sidewalks at entrances. Assume 100LF.	100	If	25.00	2,500		
18	Remove and replace sealant joints at CMU control joints. Assume 180LF.	180	lf	25.00	4,500		
19	Install door actuators at gymnasium doors at all ramp locations. Assume 6 locations.	6	ea	500.00	3,000		
20	Reattach loose shingles. Assume 100SF.	100	sf	10.00	1,000		
21	Plan for painting of exterior	5,457	sf	2.00	10,914		
22	Clean efflorescence from CMU	5,457	sf	1.00	5,457		
23	Remove plant material from CMU and from grade near CMU. Assume 100SF.	100	sf	15.00	1,500		
24			22.077	350.00	1 100		
	Install gaskets and sweeps at exterior hollow metal doors. Typical for 4.	4	ea	350.00	1,400		
25 26	Paint exterior hollow metal doors and frames. Typical for 4.  Replace carpet in offices. Assume 350SF.	350	ea sf	200.00	800		
27	Replace VCT in toilet rooms. Assume 240SF.	350 240	sf	10.00 10.00	3,500 2,400		
7.	1990 - The second of the second control of the second of t	2.10	-	10.00	2,400		
28	Patch GWB and paint interior. Assume 50SF of patching and paint all interior walls except interior face of gymnasium which are glazed block).	50	sf	25.00	1,250		
		***		40.00	,		
	Replace stained ACT. Assume 400 SF. Plan for replacement of plastic laminate cabinets and counters. Assume 20	400	sf	10.00	4,000		
30	LF of wall and base cabinets.	20	If	500.00	10,000		
	Regrade at exterior doors from gymnasium and south corridor and create						
31	an accessible egress path at exterior. Existing 4" step off concrete pad.	1	Is	5,000.00	5,000		
	Regrade around to eliminate step.						

Study Cost Estimate Fairhaven, Ma

March 26, 2018



#### Joint Recreation and Senior Center – existing site at 227-229 Huttleston Avenue

TEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
	Roofing inspection by a roofing contractor should be performed to						
	determine the cause of black staining (possible extractive bleeding or algae						
32	growth). Debris should be removed regularly from gutters and gutters	1	ls	5,000.00	5,000		
	should be inspected for condition. Dented downspouts should be						
	repaired/replaced to allow free stormwater flow.						
	Mechanical: Existing grade mounted air handling unit and all digital						
	controls have surpassed life expectancy and should be replaced. Two						
33	existing indoor air handling units including the air cooled condenser is	5,457	sf	10.00	54,570		
	approaching life expectancy and should be replaced. Replace with similar						
	types.						
	Electrical:						
34	Install new emergency back-up generator to serve both Senior Center and	1	ls	75,000.00	75,000		
34	Recreation Center (none existing).	-	13	75,000.00	73,000		
35	Change exterior parking lot lights to LED fixtures of the cutoff type. Typical	19	ea	3,500.00	66,500		
33	for 19.	20		3,500.00	00,000		
	Plumbing/FP:						
36	Replace all plumbing fixtures with water conservation type.	12	ea	2,500.00	30,000		
37	Provide new wet alarm check valve and extend system to Senior Center.	1	ls	2,500.00	2,500		
	Civil:						
	Provide pavement markings for passenger loading zone and accessible			10 000 00	10.000		
38	parking spots.	1	ls	10,000.00	10,000		
39	Repair detention basin berm to cover the exposed liner.	1	ls	10,000.00	10,000		
40	Regrade detention basin to eliminate ponding.	1	ls	20,000.00	20,000		
	Mark-ups - GC/GR, permits, overhead and profit	1	ls	241,518.75	241,519		
	Transfer of the state of the state of the designed application of the state of the				Total	3,307,594	

CURRENT 2018 CONSTRUCTION COSTS 3,307,594

Study Cost Estimate Fairhaven, Ma

March 26, 2018



### School Administration Building – existing facility at 128 Washington Street

ITEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	EST'D COST	SUB TOTAL	TOTAL COST
1	Cedar shingles need to be replaced as they are damaged, rotten, buckling and loose. Damage is especially evident on two short sides of building. Painted trim needs to be scraped and painted and wood rot was evident in many locations including wood sills.	4,864	sf	10.00	48,640		
2	Windows are mix of wood and vinyl. Wood windows need to be reglazed and some mutins are missing/broken. Vinyl windows are in good shape.	1	ls	5,000.00	5,000		
3	Exterior porch/ramp/stair assembly that needs work. Decking is loose, handrails need work, ramp needs new handrails, lattice is missing in locations, etc.	1	ls	10,000.00	10,000		
4	The precast steps at north egress door are spalled and paint is peeling.	1	Is	3,500.00	3,500		
5	On the interior, a gut renovation is required. First floor is administrative offices and two toilet rooms. Administrative offices would be a mix of half private and half open office along with a conference room. There's a kitchenette in the basement that would need to be relocated to the first floor. An IT room would need to be relocated to the first floor. The basement would be used for mechanical/utility only.	4,864	sf	125.00	608,000		
6	A HC lift should be added between the first floor and basement.	1	ls	50,000.00	50,000		
	Mark-ups - GC/GR, permits, overhead and profit	1	ls	181,285.00	181,285 Total	906,425	

Study Cost Estimate Fairhaven, Ma

March 26, 2018



### Town Hall – existing facility at 40 Center Street

ITEM	CCORE DESCRIPTION	OHANTITY		COST (SE	EST'D	SUB	TOTAL
EIVI	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	COST	TOTAL	COST
1	New accessible path through building and window to be cut down to make new entrance. Lula and interior modifications	1	Is	150,000.00	150,000		
	Deferred Maintenance Items:						
2	Remove deadbolt locks from exterior doors and install code compliant and historically appropriate panic hardware. Typical at 6 single doors and 3 sets of double doors.	9	ea	1,000.00	9,000		
3	Remove deadbolt lock from one interior egress door and install code compliant and historically appropriate lockset.	1	ea	1,000.00	1,000		
4	Remove deadbolt lock from one interior egress door and install code compliant and historically appropriate lockset.	1	ea	1,000.00	1,000		
5	Remove door knobs from 84 single interior doors and 6 pairs of interior double doors and provide historically appropriate lever style set.	96	ea	350.00	33,600		
6	Envelope, Mechanical, Electrical, Plumbing/FP: Systems analyzed under another study by another architect				TBD		
	Mark-ups - GC/GR, permits, overhead and profit	1	Is	48,650.00	48,650 Total	243,250	





# Tripp School Building – existing facility at 56 Bridge Street

					EST'D	SUB	TOTAL
ITEM	SCOPE DESCRIPTION	QUANTITY	UNIT	COST/SF	COST	TOTAL	COST
	Scope of work:						
	Gut renovation of interior to make classrooms and administrative offices.						
1	(architectural, see mep below)	21,850	sf	100.00	2,185,000		
	Exterior:						
2	Paint all exterior wood	21,850	sf	1.50	32,775		
3	Replace rotten wood trim and wood panel at basement	1	ls	10,000.00	10,000		
4	Remove algae/moss from masonry and concrete	1	ls	2,500.00	2,500		
5	Replace wood windows and clerestory with alum windows	504	sf	80.00	40,320		
6	Replace fiberglass windows with strorefront	1,540	sf	95.00	146,300		
7	Regrade at egress doors to eliminate step at threshold.	3	ea	5,000.00	15,000		
,	Review humidity issues in basement with an envelope consultant and			-,	10-000		
8	mechanical engineer. Sealing of dirt and concrete foundation may be	1	ls	25,000.00	25,000		
	advised.				48.04600#.079.07861V		
	Structural:						
	The chimney requires mortar joint repointing/brick replacement. Some						
9	brick mortar joints at the northwest corner of the building also require	1	ls	10,000.00	10,000		
	repointing.						
	The concrete steps and walks along the west side of the building are in						
10	poor condition and should be repaired or replaced. The spalled concrete	1	Is	25,000.00	25,000		
57,557	lintel above the west areaway should also be repaired.						
	There are approximately 26 brick piers/columns within the basement						
	(average height of 5'-8') that are in poor condition and require						
11	reconstruction. The piers/columns are generally within a crawlspace area.	26	ea	2,500.00	65,000		
**	Various bricks within brick walls of the basement are also deteriorated and				10004		
	require replacement/patching.						
	Mechanical:						
23	Boiler and oil tank are in good condition.						
24	Add mechanical ventilation to the building	21,850	sf	5.00	109,250		
25	Replace existing ductless split system units with new (2).	2	ea	6,500.00	13,000		
25	Install building management system.	21,850	sf	5.00	109,250		
23	Electrical:	22,000	٥.		/		
25	All electrical systems should undergo a complete gut rehab.	21,850	sf	20.00	437,000		
23	Plumbing/FP:	22,000	٥.		,,,,,,		
25	Provide new Fire/Sprinkler system.	21,850	sf	8.00	174,800		
25	Replace all plumbing fixtures	21,850	sf	5.00	109,250		
	1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-				1600 00000		
	Mark-ups - GC/GR, permits, overhead and profit	1	ls	1,052,833.50	1,052,834	4 562 270	
					Total	4,562,279	

CURRENT 2018 CONSTRUCTION COSTS 4,562,279